MISSION ABORTED (Fuel transfer problem in wings) RTB to PHNL before first drop point.

U.S. Dep't. of Commerce / OMAO / NOAA / Aircraft Operations Center

FLT ID:	20160206N1	From:	PHNL	To:	PHNL
FLT #:		Blk In:	2247z	Lnd Time:	2242z
ETD:	2100z	Blk Out:	2036z	T/O Time:	2047z
ETE:	7+30	Total Blk:	2.2	Total Flt:	1.9
Sponsoring Org:	ESRL	Program:	PAR	Purpose:	ENRR #8

AOC Flight Crew

Aircraft Commander:	MOYERS	SSA:	HILL
Co-Pilot:	MacINTYRE FRITZLER	AVAPS:	DEFEO / MILLER
Navigator:	/	Scientists:	Allen White
Flight Eng:	/	Scientists	Lisa Darby
Flt Director:	HENNING / HOLMES	Scientists	
SEB:	Charles LYNCH	Scientists:	
Crew Chief:	Visitors:	/	/

	A/C - Takeoff	Wx Station - Takeoff	A/C - Land	Wx Station - Land
Pressure	#1 1011.3 #2 1013.4	30.01 1016.1	#1 1011.0 #2 1013.0	29.96 1014.4

AS REQUIRED BY ORM	YES / NO	REMARKS:
VOLCANIC ASH		
SCIENCE MISSION WITHIN BOUNDARY LAYER		
LACK OF PRECIPITATION		
RELATIVE HUMIDITY AT OR ABOVE 80%		
LARGE AIR-SEA TEMPERATURE GRADIENT		
HIGH SURFACE WINDS		
LONG FETCH AND/OR DURATION OF SFC WIND		
SEA SALT ACCRETION FORECAST		
SEA SALT ACCRETION OBSERVED		

Dropsondes	0	Good:	0	Bad:	0	Sent: 0
AXBT		Good:		Bad:		Sent:

List other data sources in Remarks section

Remarks (Storm VDM Identifier, Mission ID, Fix Times)

Storm Number Identifier (VDM):
(ie: AL072012)

TCPOD/WSPOD Mission ID: WXWXC ELNINORR8
(ie: NOAA2 2418A SANDY)

Fix #	VDM Ob Num	Fix Time / SLP

Remarks:

Cruise #1 172.8
#2 176.9