



N43RF ERROR SUMMARY



15 April 2016
Operation Ice Bridge

Flight ID: 20160415I1

<u>Sensor or system</u>	<u>Number or Name</u>
Static Pressure Probe	PSM.2
Dynamic Pressure Probe	PQM.2
Total Temperature Probe	TTM.1
Dewpoint Temp. Probe	TDM.1
Vertical Accelerometer	AccZfilterI-GPS.1
Altimeter	AltGPS.3
INE Selection	1
Differential Attack Pressure Probe	PDALPHA.1
Differential Sideslip Pressure Probe	PDBETA.1
Dynamic Attack Pressure Probe	PQALPHA.1
Dynamic Sideslip Pressure Probe	PQBETA.1
Flight Directory	acdata/2016/MET/20160415I1

Local Met Data:	<u>Takeoff</u> (2053Z) KMCF	<u>Landing</u> (2244Z) KMCF
Aircraft Static Pressure	1013.0 mb	1013.0 mb
Tower Pressure (corrected)	1013.4 mb	1013.4 mb

Notes:

Flap Asymmetry malfunction during takeoff. All data were acquired with the flaps in the 'takeoff' position. All derived data are suspect.

Takeoff/Landing data: Data during landing and takeoff are potentially suspect. It is recommended that ground data not be used for scientific analysis.

Expendable Type	Number deployed	Number good	Number of messages transmitted
GPS dropwindsonde	0	0	0
AXBT	0	0	0
Test Sondes	0	0	0

Flight Director:
Phone #:

Ian Sears
(813) 828-4622